

Customer	Name				Exporter	MCHIBO		
	Address				Name			
Importer	Name	DTR			NZ Transport Agency Agent Code	AA177	Inspection Date	28-2-24
	Address	12 WAAP ST			Location	CCW	Check Sheet #	3394593
					Who paid for Inspection	Importation		

Chassis	GFC27-013242		Reference	AA177	
Vehicle Type	07	N/U/R or S	4	Border Check Date	07/11/2023
1st NZ Reg	1	M/Y		Engine No	W120-
Previous Country	JPN	1st Reg Date	10/2016 M/Y	Seats	8
Basic Colour	BLACK		Second Colour		
Make	NISSAN		Model	SERENA	
Sub Model		Indust Model	DAA-GFC27	Variant	28
Vehicle Year	2016	Body Type	SW	Imported LHD	NO
GVM	2150	CC Rating	1997	Engine Type	07
Assembly Type	1			Odometer	13/282
Class	LVA	No of Axles	2	Original Country	JPN
Test Regime	JDA	FC Urban		FC Ext Urban	
A/C Fitted	Y	FIS	Y	Y/N	
Gas Type	HFC134a		Tare	1710	
Completed VIN Number	7 A T O D H 3 F X 2 4 0 1 3 2 4 2				

Defects to be remedied		Rechecked		VCC Signature and ID
Section	Defect	Pass	Fail	
✓	ALL TYRES WORN	Pass	Fail	
✗	ALL BOLTS & NUTS (SIG/REP)	Pass	Fail	
✗	LOKEN APON/SIDEWINDER BRUSHES	Pass	Fail	
	CLEAN SCREEN	Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	

Comments
